

R E S T R I C T E D

ELECTRICAL AND MECHANICAL
ENGINEERING REGULATIONS
(By Command of the Army Council)

TELECOMMUNICATIONS
A 522

MINIATURE REPAIR TECHNIQUES

Erratum

Note: This Page 0 will be filed immediately in front of Page 1, of Issue 1 dated 14 Jul 53.

1. The following amendment will be made to Issue 1 of this Regulation.

Page 5, para 13, lines 7 to 9

Delete: "When both the terminating lead and the tag have been tinned the lead should be either wrapped round the tag or put through the hole in the tag and nipped lightly with pliers to make a good mechanical joint".

Insert: "When both the terminating lead and the tag have been tinned, the lead should be put through the hole in the tag, bent one-half turn round and nipped lightly with pliers to make a good mechanical joint".

57 faint/2878

Issue 1, 20 Nov 53

Distribution - Class 800. Code No. 2

Page 0

MINIATURE REPAIR TECHNIQUES

1. The following EMERS are now cancelled. They are superseded by WORKSHOPS F 100.

2.	Page	0	Issue 1	dated	20 Nov 53
	"	1-10	" 1	"	14 Jul 53
	"	1001-1002	" 1	"	14 Jul 53.